



**Development Services  
Building Safety/Codes**  
1221 McArthur Road  
Maryville, TN 37804-5906  
Phone: 865-681-9301 Fax: 865-681-9501



## **NOTICE**

### **REINSPECT FEES ENFORCED**

Effective February 1, 2020 Re-Inspection Fees will be enforced as follows:

\$75.00 Residential  
\$100.00 Commercial

All permits are subject to a Re-Inspection Fee under the following conditions:

- 1) Scheduled inspection time is not cancelled one (1) hour prior to appointment, by calling the office, not inspector.
- 2) Not ready for inspection (considered failed inspection).
- 3) Access not provided to property at time of inspection, such as gate codes, etc.
- 4) Failed inspection.
- 5) Multiple cancellations within the one (1) hour period on the same permit could also result in assessed fees.

If a re-inspect fee is assessed, no future inspections will be scheduled until all fees have been paid.

Re-Inspect fees can be paid via credit card by calling (865) 681-9301. Cash and check is also accepted by visiting the office at 1221 McArthur Road, Maryville, TN 37804.

Thank you for your cooperation in this matter to ensure that everyone is allowed an opportunity for a timely inspection.

**NO PAYMENTS WILL BE ACCEPTED IN THE FIELD**